

## CASE STUDY - CAR DETAILING

CS012

**Client:** Car Detailing Company

**Situation:**

A car remained static for many months in a situation where moisture was entering into the car through the boot. The moisture worked its way into the cabin of the car. Mould took hold and quickly grew on most internal surfaces within the car.

**Treatment:**

All internal surfaces within the car were sprayed with 250ml of SAN-AIR Surface Mould Remover. The car was then left to dry over the weekend. When the client returned on Monday morning, he noticed that the internal surfaces were covered with a powdery, flaky substance, which appeared to be dried up mould. The surfaces were then vacuumed with a commercial vacuum cleaner. The AFTER photos were taken directly after vacuuming. SAN-AIR followed up three months later and the mould had not returned.

**Conclusion:**

Visible mould can be easily and quickly neutralised and removed, even in severe cases of contamination.

